


DEMOLITION NOTES THIS SHEET

- 1 REMOVE HWS/HWR, CWS/CWR AND D PIPING, HANGERS AND SUPPORTS COMPLETE TO POINT INDICATED.
- 2 REMOVE WALL MOUNTED THERMOSTAT AND CONTROL LINES COMPLETE.

ASBESTOS AND LEAD PAINT NOTE

AN ASBESTOS INSPECTION WAS PERFORMED AND ASBESTOS CONTAINING MATERIALS WERE FOUND GENERALLY IN THE AREAS INDICATED IN THE ASBESTOS SURVEY/INSPECTION REPORT WHICH IS AVAILABLE TO THE CONTRACTOR(S) FOR HIS INFORMATION. ASBESTOS CONTAINING MATERIALS HAVE BEEN REMOVED UNDER A SEPARATE CONTRACT.

A LEAD-BASED PAINT INSPECTION WAS PERFORMED AND LEAD-BASED PAINT WAS FOUND IN THE AREAS INDICATED. THE CONTRACTOR SHALL BE RESPONSIBLE WITH ALL REQUIREMENTS OF THE VIRGINIA OCCUPATIONAL SAFETY AND HEALTH ADMINISTRATION REGULATIONS LEAD-BASED PAINT PROTECTION OF WORKERS.



KEYPLAN
NO SCALE

GRAPHIC SCALES

3/16" = 1'-0" 0' 5' 10' 20'

DEMOLITION FLOOR PLAN - MECHANICAL PIPING
SCALE: 3/16" = 1'-0"


nbij ARCHITECTURE
A Professional Limited Company
GROVE PARK SQUARE
11537-B NUCKOLS ROAD
Richmond, Virginia 23069
P: (804) 273-9811 Fax: (804) 273-9843



**RAPPAHANNOCK
COMMUNITY COLLEGE**
CAMPUS RENOVATIONS
WARSAW + GLENN'S, VIRGINIA
PC: 260-17712

**GLENN'S CAMPUS
DEMOLITION FLOOR
PLAN - MECHANICAL PIPING**

Date: JANUARY 13, 2010
REVISIONS
NO. DATE



Sheet
MD2.6G
File Number
XX